

# TB17-101R/A (TB16-114R/A)

# TECHNICAL SERVICES BULLETIN

To: Residential Distributors and Dealers

Aftermarket Distributors and Dealers

Date: 02/15/2017

Subject: Update to bulletin TB16-114R/A – T4B(Q)E, \*SH4BE

Micro-Channel Heat Pump Coil Leaks

## **DESCRIPTION:**

Nortek Global HVAC has been made aware of an issue related to Micro-Channel heat pump condenser coils. This issue can cause a leak at the bottom header tube between the Micro-Channel tube and the bottom header.

#### **MODELS AFFECTED:**

\*T4B(Q)E, \*SH4BE

### **ACTION REQUIRED:**

If the coil leaks at the bottom header, please contact the Nortek Global HVAC Technical Services department for verification of the leak area. Nortek Global HVAC will allow a replacement of the heat pump via the QP process and a \$250 labor allowance.

#### **QUESTIONS?**

Please contact the Nortek Global HVAC Technical Services department at 1-800-422-4328.

**CONFIDENTIALITY POLICY:** Bulletins are not for public display, web posting, or dissemination to non-Nortek Global HVAC partners. Distributors may post the bulletin ONLY behind a secure firewall that requires password access, and where the folder cannot be crawled by web search engines.