

AVIDYNE

IFD5XX | IFD4XX SERIES NAVIGATORS

GPS ROLLOVER CORRECTION GUIDANCE



To obtain the GPS Rollover Software, Instruction and Video Tutorial follow this link:

https://lz314.infusionsoft.com/app/form/gpsrolloverupdate

Single IFD Installation



Request for GPS Roll Over Update

Aircraft Owner's First N

Aircraft Owner's Last Name *

Owner's Phone Number *

Owner's Email *

Tail Number *

IFD Model Installed in #1 *

IFD Model in #2 (Enter none if only 1 installed) *

Jorge

Hernandez

321-751-8439

JHernandez@Avidyne.com

NTEST

IFD550

NONE

By pressing the submit button to request the software, you acknowledge that your software is at R10.2.x.

Submit

Dual IFD Installation



Request for GPS Roll Over Update

Aircraft	Owner's	First I	Name *

Aircraft Owner's Last Name *

Owner's Phone Number *

Owner's Email *

Tail Number *

IFD Model Installed in #1 *

IFD Model in #2 (Enter none if only 1 installed) *

Jorge

Hernandez

321-751-8439

JHernandez@Avidyne.com

NTEST

IFD550

IFD440

By pressing the submit button to request the software, you acknowledge that your software is at R10.2.x.

Submit



Upon Selecting SUBMIT, please allow up to 10 minutes for the email to arrive.

AVIDYNE

Thanks Jorge! We will email you the information shortly. Look for an email from pilotsupport@avidyne.com. If you do not receive it within 10 minutes, please check your spam folder.

Click Here for Video







Click on the IFD to take you to watch the video on how to update your IFD

Attached please find your GPS roll-over update and instructions on how to implement it. It is important that you watch the video first and follow the instructions on the Service Bulletin.

Reach out to us should you have any questions.

Pilot Support
pilotsupport@avidyne.com

Click here to download update

Click here for instructions





Unsubscribe

Avidyne Corporation 710 North Dr Melbourne, Florida 32934 United States (800) 284-3963



Click Here for Software







Click on the IFD to take you to watch the video on how to update your IFD!

Attached please find your GPS roll-over update and instructions on how to implement it. It is important that you watch the video first and follow the instructions on the Service Bulletin.

Reach out to us should you have any questions.

Pilot Support pilotsupport@avidyne.com


Click here for instructions





Unsubscribe

Avidyne Corporation 710 North Dr Melbourne, Florida 32934 United States (800) 284-3963



Click Here for Service Bulletin







Click on the IFD to take you to watch the video on how to update your IFD!

Attached please find your GPS roll-over update and instructions on how to implement it. It is important that you watch the video first and follow the instructions on the Service Bulletin.

Reach out to us should you have any questions.

Pilot Support pilotsupport@avidyne.com



Unsubscribe

Avidyne Corporation 710 North Dr Melbourne, Florida 32934 United States (800) 284-3963



SERVICE BULLETIN

Document Number: 601-00182-048

Title: IFD5XX-4XX Series Upgrade to 10.2.x.0.A

Revision: 00

Date: 08 February 2019

1. Planning Information

1.1 Distribution/Eligibility

This Service Bulletin may be distributed only to those groups indicated below with a check mark:

Group	Distribution?
Avidyne internal & Field Support Personnel	✓
Avidyne-authorized Service Facility	✓
Avidyne Web/FTP Post	✓
Avidyne-authorized Installer	✓
Avidyne OEM customers	✓
End-use customers, owners and operators	

The Accomplishment Instructions contained in Section 3 may only be performed by appropriately authorized personnel with appropriate repair authorization station or repairman certificate.

1.2 Effectivity/Compatibility

This Service Bulletin applies to Avidyne 700-00182- () and 700-00179-() Integrated Flight Display (IFD) with Release 10.2.0.0, 10.2.1.0 or 10.2.2.0 software installed. To determine what version of software is installed, press the "AUX" gape key and navigate to the "SyS" tab. Select the "Software" Line Select Key (ISK).

1.3 Concurrent Requirements

None.

1.4 Reason

Installation of this software update addresses the GPS date rollover that will occur on April 6, 2019. This service bulletin is required to upgrade IFDs, p/n 700-00182-() or 700-00179-(), to Release 10.2×0.4 software. Specifically:

- 10.2.0.0 will become 10.2.0.0.A
- 10.2.1.0 will become 10.2.1.0.A
- 10.2.2.0 will become 10.2.2.0.A

 Revision: 00
 Service Bulletin 601-00182-048

 Date: 08 February 2019
 Page 1 of 15



Thank You