

TECHNICAL SERVICES BULLETIN

To: Aftermarket Dealers and Distributors
From: Technical Service
Date: 01/11/2017
Subject: M1 Pressure Switch

DESCRIPTION:

Recently, Nortek Global HVAC has updated the pressure switch for M1 gas furnaces. This improved pressure switch should eliminate the possible issue of the gas valve clicking open and closed at the start of ignition.

MODELS AFFECTED:

M1 model furnaces manufactured from June 2015 to November 2016. The new switch went into production December 2016.

ACTION REQUIRED:

If the pressure switch should cause the gas valve to start chattering, replace the pressure switch. Follow normal warranty policies and procedures.

The new pressure switch part number **1010775R**.

QUESTIONS?.

Please contact Nortek Technical Services at 1-800-422-4328.



CONFIDENTIALITY POLICY: Bulletins are not for public display, web posting, or dissemination to non-Nortek Global HVAC partners. Distributors may post the bulletin ONLY behind a secure firewall that requires password access, and where the folder cannot be crawled by web search engines.