

SERVICE BULLETIN

International Comfort Products



Number: SB2015

Issued: 12/31/20

Title: Residential & Commercial Systems
SB Policy Update

Revision:

Expires: 6/30/21

Category: Informational

Dept: RES and CML
Quality

Dealer Bulletin Number: None

Residential & Commercial Systems (RCS) Product Policy Bulletins published prior to December 31, 2020 have been reviewed to determine new expiration dates. Except for the terminated bulletins noted below, the listed Policy Bulletins will continue to be eligible for credit following December 31, 2020 (or as otherwise noted).

The expiration dates of the bulletins included on this list will be updated again by June 30, 2021. Please advise your warranty department that the new expiration dates listed in this Bulletin supersede the originals.

Bulletins terminated from the previous Policy Update (SB2010):

SB1914 Humidi-Mizer Solenoid Installed Incorrectly

Residential & Commercial Systems Active Policy Bulletins

BULLETIN No.	<u>TITLE/SUBJECT</u>	NEW EXPIRATION DATE
SB15-0012	PTAC/PTHP Mandatory Safety Recall	6/30/21
SB18-0010	5-Stage Inverter Failures	6/30/21
SB18-0020	Indoor Blower Motor Quality Issues (E3 error)	6/30/21
SB18-0021	Non-WIFI Observer® Software Revision Verification and Update	6/30/21
SB1909	Fan Coil RBC (Endura Pro) Replacement Control Module 2015 mfg.	4/30/21
SB1910	Fan Coil Broad Ocean (Digi) Replacement Control Module 2015 mfg.	4/30/21
SB2004	Base Pan and Crankcase Heaters	6/30/21
SB2006	FER Communicating Furnace Control Software Update – Dual Fuel Applications	6/30/21
SB2009	DLCSRAH12AAJ Replacement	6/30/21