

# TECHNICAL SERVICE BULLETIN

## TSB C-GN-OT-0094

**Date:** April 10, 2026  
**To:** All Service and Parts Managers  
**From:** Technical Services Department  
**Subject:** PCBBF140S Supplier Error

This is an important Technical Service Bulletin to inform our customers of a supplier issue on the PCBBF140S replacement control boards. A supplier error has been identified on certain PCBBF140S replacement control boards. The inducer and ignitor 120V L1 connections were installed with an incorrect 4-pin connector instead of the correct 2-pin connector. The left image below shows the incorrect 4-pin connector, the middle image shows the potentially affected 2535 date code on the box (other date codes may also be affected), and the right image shows the correct 2-pin connector.

Distributors should inspect **all** PCBBF140S inventory for the incorrect 4-pin connector. For any affected boards, photograph each one and send the photos along with a complete list of affected boards to Daikin Order Services.

Once Daikin Order Services has received the photos and confirmed the quantity of incorrect boards, a credit will be issued, and distributors will be authorized to field scrap the affected boards. **Do NOT field scrap any boards until receiving authorization from Daikin Order Services.** To receive replacement parts, place an order directly with Daikin Order Services.

**Incorrect Connector**



**Correct Connector**



If you have technical questions, please call 1-855-DAIKIN1, option 2 then option 1, or e-mail [TechnicalServicesDaikin@daikincomfort.com](mailto:TechnicalServicesDaikin@daikincomfort.com).

DAIKIN COMFORT TECHNOLOGIES NORTH AMERICA, INC.

19001 Kermier Road • Waller, TX 77484 • (713) 861-2500 • [www.daikincomfort.com](http://www.daikincomfort.com)

Daikin products are subject to continuous improvements. Daikin reserves the right to modify information in the bulletin without notice and without incurring any obligations.

Amana® is a registered trademark of Maytag Corporation or its related companies and is used under license. All rights reserved.