



Inspection Report

This is the sub title

Details

Inspection Type	Inspection #
Foundation and Backfill	INSP-1139
Project Address	Property Lot
PLAN 1279 PT QUEENSBORO ST RP 12R-21042 PART 89	
Permit #	Status
PRM-2024-0016	Scheduled

Schedule

Inspector	Inspection Date
mdawe20 (Matthew Dawe)	2024-05-30
Start Time	End Time
09:00	09:30

Tasks

Name	Status	Comments
a) Weeping tiles of minimum 4" or 100 mm are provided at the bottom of every foundation wall that contains the building interior 9.14.3.2.(1) & 9.4.2.1.(1)	☑Completed	
b) 6" Stone Cover around Weeping Tile is provided and continuous.	☑Completed	
c) Anchor Bolts on foundation walls are provided at or lesser than 2.4m o/c --> 9.23.6.1	☑Completed	
d) Window Wells below grade are provided with drainage. 9.14.6.3.(1)	☑Completed	
e) Foundation Walls below grade appear to be dampproofed. 9.13.2.1	☑Completed	
f) Foundation Walls below grade appear to be waterproofed. 9.13.3.1	☑Completed	

Inspection History

Date	User	Inspector	Inspection Date	Status	Comments
2024-08-21 15:24	supportbbi	mdawe20 (Matthew Dawe)	2024-05-30 09:00 - 09:30	Rescheduled	
2024-05-29 16:09	supportmd	jpsingh (Japinder Singh), mdawe20 (Matthew Dawe)	2024-05-30 09:00 - 09:30	Rescheduled	
2024-05-09 14:53	supportjs	jpsingh (Japinder Singh)	2024-05-09 09:00 - 09:30	Scheduled	
2024-05-09 14:53	supportjs	jpsingh (Japinder Singh)	2024-05-09 09:00 - 09:30	Conditional Pass	
2024-05-09 14:53	supportjs	jpsingh (Japinder Singh)	2024-05-09 09:00 - 09:30	Scheduled	
2024-05-09 14:53	supportjs	jpsingh (Japinder Singh)	2024-05-09 09:00 - 09:30	Failed	
2024-05-09 14:53	supportjs	jpsingh (Japinder Singh)	2024-05-09 09:00 - 09:30	Scheduled	

Notes

Date	Note	Added By
------	------	----------

Pictures



This is the footer

Inspector Signature

2024-05-30
Date